500 Cardigan Road, Shoreview, MN 55126 USA tel 651 490 2811 + toll free 800 874 2811 + fax 651 490 3824 + web www.tsi.com

July 2, 2015

Subject: End of Repair Notification — TSI DustTrak Model 8520 Aerosol Monitor

Dear Valued Customer:

TSI is committed to providing the best possible product support. As products are updated with more advanced technology, there is limited part availability from our vendors to support the previous generation.

Thus, due to the recent part obsolescence, <u>TSI will officially discontinue repair for the DustTrakTM Model 8520 Aerosol Monitor effective December 31, 2015</u>. We will continue to provide calibration services on this instrument.

Recommended replacement instruments to support your dust monitoring needs include the DustTrak II Model 8530 and the DustTrak DRX Model 8533 Aerosol Monitors. View the following links for product information on the 8530 or 8533 DustTrak Aerosol Monitors and applicable trade-in promotion.

Please contact us at 800-874-2811, at answers@tsi.com, or by contacting your TSI Sales Representative with any questions.

Sincerely,

Troy Tillman
Business Director
Test & Measurement Instrumentation