



TSI INCORPORATED

500 Cardigan Road, Shoreview, MN 55126 USA
tel 651 490 2811 + toll free 800 874 2811 + fax 651 490 3824 + web www.tsi.com

June 2, 2015

**Subject: End of Repair Notification —
TSI PortaCount Plus Models 8020 and 8028 Respirator Fit Testers**

Dear Valued Customer:

TSI is committed to providing the best possible product support. As products are updated with more advanced technology, there is limited part availability from our vendors to support the previous generation.

Thus, due to the recent part obsolescence, **TSI will officially discontinue repair for the PortaCount® Plus Models 8020 and 8028 Fit Testers effective December 31, 2015.** We will continue to provide calibration services on these instruments.

Recommended replacement instruments to support your respirator fit testing needs include the PortaCount Pro Models 8030 or 8038 Respirator Fit Testers. View the following links for product information on the [8030](#) or [8038](#) PortaCount Fit Testers and applicable [trade-in promotion](#).

Please contact us at 800-874-2811, at answers@tsi.com, or by contacting your TSI Sales Representative with any questions.

Sincerely,

Troy Tillman
Business Director
Test & Measurement Instrumentation